



HOW TO ORDER A GROUNDING SET

In addition to the specifying criteria above, each part of a grounding set requires certain choices:

1. Clamps

ASTM designations for Type, Class, and Grade given for clamps in this section.

2. Ferrules

Copper or aluminum. Plain or threaded.

3. Cable

Length required to reach application distances.

ASTM Type I with black or yellow elastomer jackets for temperatures from -40° F (-40° C) through +194° F (+90° C).


ASTM Type III with clear thermoplastic jacket for temperatures from +14° F (-10° C) through +140° F (+60°) should be used only in well-ventilated areas.

4. Support Stud

This option recommended on only one clamp to help control lifting the set to the first clamp attachment point.

5. Shrink Tubing

This translucent option recommended for stress relief and inspection of cable strands between ferrule and jacket.



INSTALLATION INFORMATION

Several installation training aids are available on request.

Chance videotapes and technical manuals - provide more details on proper installation. **Consult your Reliable representative for any assistance.**