



*Tooling solutions for the power utility industry.*

## CW - CHANCE TELEHEIGHT

This handy little instrument helps to figure quickly and accurately the heights of poles, trees, buildings, or conductor clearance. A lineman can be taught in a few minutes to use it. The diagram at left shows how it works. Sight point A through the Teleheight and move backward or forward until the bubble centers on the hair line, which will be point C. Measure distance from C to D and add distance BC to find correct height. Leather case (2-1/4" x 4-1/4") has belt loop (Included). (1-1/4 lb.)



TELEHEIGHT

## DILLON - 5" MODEL AP DYNAMOMETER

The Dynamometer has proven to have limitless versatility as a tension, traction, and weight measuring instrument. This tool is used for adjusting tension on guy wires; field testing chain, rope, wire -- anything requiring precision force or tension measurement in the field.

Model AP Dynamometers represent the very latest state of the art in force measurement. Exclusive antiparallax dial and pointer simplify readings and answer the demand for ever closer tolerances. Tare loads up to 20% of capacity may be cancelled by means of zero control. The units can be operated in any position - horizontal, vertical, or flat - without effecting the accuracy of the unit. Pinion gears, sector gear, and shafts are mounted in precision aircraft bearing, permanently sealed against dust and dirt. Oiling is never required.

Model AP Dynamometers are rated at 1/2% of full range on both ascending and descending loads in all capacities up to 100,000 lbs. The ultimate safety factor on most models is 5:1. An official Certificate of Calibration, dated and signed, accompanies all new, repaired, or verified Dynamometers.


### Standard Model AP Dynamometer includes:

Dynamometer, shackles and pins, maximum pointer, zero adjust for tare and molde plastic carrying case on all 5" models.

**30006-0050 5,000 x 50 Dynamometer**

**30006-0084 10,000 x 100 Dynamometer**

**30006-0092 15,000 x 100 Dynamometer**



DYNAMOMETER



**IF YOU DONT SEE WHAT YOU NEED  
CONTACT RELIABLE EQUIPMENT  
800-966-3530**

**TO ORDER CALL: 800-966-3530 OR FAX: 215-357-9193**